



3DYPHW0D6WST0SPW

26W0DWD0E7D8RDP

Improve overall performance and extend product life with routine factory maintenance.

Scope of Work:

- Run for proper operations
- Remove paint plumbing - clean and reinstall
- Clean all screens in paint filters and manifolds
- Replace gaskets on paint tank lids
- Disassemble paint guns and install rebuild kits
- Disassemble high pressure pumps - inspect, clean and rebuild
- Disassemble diaphragm pumps - inspect, clean and rebuild
- Remove end of heat exchangers - clean heat exchangers, replace ends and install new gaskets
- Check regulators and gauges for proper operation
- Test all systems for leaks and proper operation
- Recalibrate skip line over a measured course

6WDWDW

\$5,000.00 USD = 32 Hours of Maintenance & Training

Additional/required parts available for purchase.

Labor and parts installed by the MB Technician will be covered by our factory warranty for the period of one year from date of installation.

Travel and expenses additional if incurred.

Customer Responsibilities:

- Remove of all the paint from the paint system
 - Flush water through the entire paint system from the paint tanks through the paint guns
 - Drain the flush water out of the system, purging it with air to get as much of the water out as possible.
 - Immediately after blowing the system dry with air, add 25 gallons of RV antifreeze to each paint tank
 - With low pressure on the tanks, purge both yellow and white systems with RV antifreeze through the entire system, through the paint guns
 - Remove all the water from the flush tank
 - Blow the system out with air until dry and purge with RV antifreeze
- Communicate any known issues to MB prior to technician's arrival

Schedule Your Service Today

Patricia Botsford, After Sales MB Pavement Marking

- Patricia.Botsford@Aebi-Schmidt.com
- 570.599.2158
- www.m-bco.com



www.aebi-schmidt.com

M-B Companies
3DYHPHW0DUTSPHW
 95 Blessing Dr. Muncy, PA 17756
 Phone 800-323-2900 www.m-bco.com

Scan to discover
 M-B Companies on YouTube
 Technical data is subject to change.
 Illustrations are not binding.

© Aebi Schmidt Group, 07/2022

